

GENERAL REMARKS

The analysis and recommendations submitted in this report are based upon the available information derived from the soil borings performed. Since it is possible for variations in soil conditions to exist between boring locations, it is recommended that the soil at the base of all footings be inspected by an experienced soil engineer to assure that suitable bearing is obtained. It is also recommended that the placement of all fill be inspected and controlled by an experienced soil engineer to assure conformance with recommendations. If you wish, we would welcome the opportunity to perform any of the herein recommended inspection services for you during construction. In addition, we would be pleased to review the plans and specifications after they have been prepared for the project so that we might have an opportunity of commenting upon the effect of soil conditions on the design of the foundations.

This report has been prepared in order to aid in the evaluation of this site and to assist the architect and/or engineer in the design of the project, based on our understanding of the design details, criteria and utilization of the structure as outlined herein. It is intended for use with regard to the specific project discussed herein and any change in design or location should be brought to our attention so that we may determine how these changes may affect our recommendations. Also, if our understanding of the design details and utilization of the project is not correct, we should be promptly informed of the correct data so that we may alter our recommendations as appropriate.

US EPA RECORDS CENTER REGION 5



486661